## Grenada Manufacturing, LLC

## "A Global Leader in Metal Fabrication"

635 Hwy 332 Grenada, Ms 38901 662-226-1161 Fax

Fax

July 8, 2002

Narindar Kumar, Chief RCRA Programs Branch USEPA Region IV Atlanta Federal Center 61 Forsyth Street Atlanta, GA 30303-8960

RE: WET WELL INSPECTION – JULY 2, 2002, GRENADA MANUFACTURING, LLC, EPA ID No. MSD 007 037 278

Dear Mr. Kumar:

As requested by Mr. Don Webster, the Wet Well (SWMU 12) was cleaned and inspected on July 2, 2002. The following items were noted.

- 1. Approximately two cubic yards of material removed from SWMU 12 is awaiting analysis and proper disposal.
- 2. The protective coating applied to SWMU 12 is intact and in place.
- 3. No corrosion, cracks or separation between the floor and wall was apparent.
- 4. The Wet Well is in good shape with no noticeable loss of integrity.

Electronic copies of the attached photos of SWMU 12 have been distributed to Mr. Don Webster of your office. If you have any questions, please contact me at (662) 226-1161. Thank you.

Sincerely,

Don Williams EHS Coordinator

dwilliams@grenadamfg.com


cc: Don Webster, USEPA
Louis Crawford, MDEQ
Chet Melton, Grenada Manufacturing
Greg Mackin, Collins & Aikman
John Bozick, Arvin Meritor

Wall of Wet Well - 7/2/02

Wet Well emptied but prior to cleaning - 7/2/02



Test plug in process sewer line - 7/2/02



Wet Well - union between wall and floor - 7/2/02



Wet Well - union between wall and floor - 7/2/02



Wet Well - floor underneath suction pipe - 7/2/02

